DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/26/2014 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		155761	B. WING _	3. WING		03/20/2014	
NAME OF PROVIDER OR SUPPLIER BROWNSBURG MEADOWS				STREET ADDRESS, CITY, STATE, ZIP CODE 2 E TILDEN BROWNSBURG, IN 46112			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI) TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE
K 000	INITIAL COMMENTS		K	000			
	licensed residential be the 500 Unit was cond Department of Health 483.70(a). Survey Date: 03/20/1 Facility Number: 011: Provider Number: 15 AIM Number: 20085. Surveyor: Mark Cara Specialist At this Life Safety Conderned Preoccupancy Survey found in compliance was conderned to the survey for	r for the conversion of 11 leds to 11 certified beds in ducted by the Indiana State in accordance with 42 CFR 4 367 5761 1590 her, Life Safety Code de and Environmental r, Brownsburg Meadows was with Requirements for					
	Subpart 483.70(a), Lir 2000 edition of the Na Association (NFPA) 1 Chapter 18, New Heat 410 IAC 16.2-3.1-19 I Standards of the India for Comprehensive car. This one story facility Type V (111) construct The facility has a fire detection in the corridothe corridor. The facility has directly the corridor to the fire a resident sleeping room.	01, Life Safety Code (LSC), alth Care Occupancies and Environment and Physical ana Health Facilities Rules are facilities. was determined to be of extion and fully sprinklered, alarm system with smoke ors and in all areas open to lity has smoke detectors alarm system installed in all ms. The facility has a a census of 131 and had a					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/26/2014 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED		
		155761	B. WING			03/20/2014	
NAME OF PROVIDER OR SUPPLIER BROWNSBURG MEADOWS				2	STREET ADDRESS, CITY, STATE, ZIP CODE E TILDEN BROWNSBURG, IN 46112		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	Continued From page All areas where reside were sprinklered. All services were sprinkle Quality Review by Ro	e 1 ents have customary access areas providing facility	TAG		DEFICIENCY)	ATE	DATE